


Front Helm Flip and trace for Right Side 6mm foam front 2 front 3 front 5 front front K-45


Center Helm


When putting these peices together start with the side with the red dots.


Flip and trace for Right Side 6mm foam



Center Helm







Neck 6mm m_{iddle} 4

